Approved For Release 2002/10	0/25: CIA-RDP72B00464R000400070049-2264 LP 2264 ECPs
	OSA -0545-66
	<b>24</b> JA. 1966
Subject: ECF GR-26 Recorder	r Adapter Plate
Dear Nat,	
This letter confin	rms my telecon of 19 January 1966, STATINTL
damage to the aircraft's reco	lled. However, we have learned that order cooling air outlet frequently ter plate. We recommend that you I of 6 each of the new adapter plates.
The preferable met of inserting a new item of Affollows:	thod of accomplishing the end result E to replace Part Number 531A970-034-101
a. The new Recis initial AGE and as such is under the production contract	corder Adapter, Part Number 531A970-042-101, s an integral part of initial provisions t.
List (Fig 1) to the FSO and thereon including distribution BN-4, BN-5, and BN-6. In the	ctor shall submit a new AGE Requirements the SFO with appropriate information on of the new AGE items to locations at a remarks section of the Figure 1, indicate the required disposition of the superseded , estimated cost, etc.
	etor shall accomplish the necessary changes as these are affected by this new AGE
	Best regards,
STATINTL	Canada
Copy:	George

STATINTL

## Approved For Released 2002/10/25: CIA-RDP72B00464R000400070049-2 ( ) junge w/ancl )

AKP-I-4661 3 September 1965

T0:

12+1) 20-1-2

SUBJECT:

Recorder Adapter Plate

(AGERL Item 11, Revised 1 Sept. 1965)

ENCLS:

A - ECP GR-26

B - Nat/Rus Agreement G-146

C - AGERL Item 11, Revised 1 Sept. 1965

Enclosure B indicates coordination between GR and ADP on the Recorder Adapter Plate. The revised drawing incorporating ADP's marked print will be returned to ADP for approval on 3 September 1965.

It is requested that Enclosure A be approved and quantitites indicated on Enclosure C be approved. I have checked BW-4 (our personnel) and they desire a new plate also. In addition to the costs included in ECP-26, \$1,400 will be required on the Prototype Program. LP-2263

NAT

N/mj encls.

cc: Charlie Fred/Bob Joe M. Mich Houst 12

854 (10) MA